

Descriptor	Item Update Summary
Accessories	Suction Guide 104 PacDOR models
	Resolved Expansion equipment tank volume error (Incident #114355)
	Dirt & Air Separators Submittal correction (Incident #115212)
Boosters	NVS-332010 Booster model should be VMS-32:01B
	Update Booster Configurator required for NA Markets (Incident #114689)
Fire Systems	Error during rules processing: Item JockeyPump (Incident #114498)
	Fire pump selection missing option set for pump (Incident #115739)
	Update FireMtrRiserESHSCElec_v2 Matrix (Incident #115937)
	FireVILCouplingAssyConstraints_v2 Matrix Update (Incident #116141)
Guidance	Expired Quote notification (User mentoring enhancement)
	Replacement Fire Pump serial number requirement (User mentoring enhancement)
	Quantity entry alert (User mentoring enhancement)
Heat Exchangers	Resolved inspection 3004 on shell and tube
	Resolved ADEPT PFX Configurator error (Incident #114324)
Lead Times	Shipment indicator description update for shipment indicator tool
	Showing Wrong Shipment Time for Replacement DEPC (APR market)
	New DEPM IVS pump range - ADEPT Shipment Indicator update for MEA and APR Market (Incident #111046)
	MFW: Shipment Indicator Violation - Buy American option (Incident #113281)
	Updates to Shipment Indicator (Incident #113989)
	Shipment Indicator - Updates (Incident #115544)
	Update INDIA Shipment Indicator for Fire System (Incident #116006)
Order Submission	Kaori Integration with ADEPT
	Getting Error on Place order after clicking on Finish Button.
	Multiplier level warning message (quote with std and config item) even though standard item has the correct default multiplier (US CDB/UK CDB Markets)
	Pump house not creating NCP request and providing price which appears inaccurate. (Incident #115066)
Parts	Update DAS Part numbers from 125psi to 150psi
	Services&Parts: With Ref TP#50608: Add additional Line details in the cart
	Trimmed impeller not found (Incident #87610)
	Volute/Casing (Incident #115104)
	Recommended parts kits print in documents - add an option to select from customer (Incident #116135)

Descriptor	Item Update Summary
Pumps	Suction Guide Selection Unavailability (Incident #113349)
	Resolved error on click of curve envelope - VS 4600 (125-380L-2p-225kW) (UK Market)
	Manufacturing Rules update for Medium Pumps Tango & SGs (DCR-2024-009)
	Removed VMS 15 +NCP price (DCR-2024-004)
	VMS64 - Add new engine and configuration work (DCR-2024-003)
	Engine and configuration update for Medium Pump Tango & SGs (DCR-2024-009)
	Remove the new pumps from manual select for release - re:Medium Pump Tango & SGs (DCR-2024-009)
	VMS64 and Tango 6" configurations updated
	Medium pump 6" 3D model issue resolved
	Medium pump tango 4332 & 4362 configuration update
	Faulty motor line (Incident #94862)
	Resolved 4280 8x6x13 Curve Display Error (incident #111968)
	Replacement drive configurator update(incident #113127)
	Adept Motor Curves (Incident #113811)
	Remove 3750 selections (Incident #114445)
	Review DEPM SI (SQXN004804_3) (Incident #114449)
	Complete pump vs bare shaft pump (Incident #114853)
	Pump Manager Issue (Incident #114967)
	575V for USA (OEM) (Incident #115223)
	SMART Start-up not printing on ADEPT (Incident #115921)
Update Daikin pump configurator - selective DAIPUMPs show show part 427828-011 instead of 427828-111 (Incident #115510)	
JCI pump configurator variant frame size (Incident #116044)	
4300 CCS- DBF construction with H-Insulation (Incident #116825)	
Selection	Pump Search Grid label changes
	Getting error while Importing Xml to the Quote
	Adept Select- Download with Specification & Single Curve on Schedule page giving Error-All Market.
	Pumps manual select not working for 4300 0205-002.0 where head is passed as zero
	Obsolete models from Med pump 6" with price increase of 30% adder 4300 0308-020.0 and 0308-025.0
	Changes / Additions to TM65 report data
	Remove suction connection and discharge connection from drop down (India boosters)
	Rename booster name to DE 6800 BOOSTERS-QPR (India China)

Descriptor	Item Update Summary
	Routing Changes: Buy American orders (BA KIT) (Incident #50534)
	Motor hard to find (Incident #114779)
	DE4300 1217-150.0 Pump selection (Incident #115076)
	ASU TES Selection (Incident #115148)
	V-cut information not populating on Medium pump Cimco selection (Incident #117317)
	Routing time on BOOSTER/128218 is off (Incident #117388)